

序号	报告编号	发布日期	结论	影像资料
1	GX-B1341/21-9-23218	2023. 9. 1	综合判定：合格。	
2	GX-B1341/21-9-23219	2023. 9. 1	综合判定：合格。	

3	GX-B1341/21-9-23220	2023. 9. 1	综合判定：合格。		 A photograph showing two workers in red safety suits and helmets standing in a dark tunnel. The workers are facing forward, and the scene is dimly lit, with a bright light source visible in the background. The date '2023-08-26' is printed in the bottom right corner of the image.	
4	GX-B1341/21-9-23221	2023. 9. 1	综合判定：合格。		 A photograph showing two workers in red safety suits and helmets standing in a dark tunnel. The workers are facing forward, and the scene is dimly lit, with a bright light source visible in the background. The date '2023-08-26' is printed in the bottom right corner of the image.	

5	GX-B1341/21-9-23222	2023. 9. 1	综合判定：合格。	 <p>2023-08-26</p>
6	GX-B1341/21-9-23223	2023. 9. 1	综合判定：合格。	 <p>2023-08-26</p>

7	GX-B1341/21-9-23224	2023年9月1日	综合判定：合格。	
8	GX-B1341/21-9-23225	2023年9月1日	综合判定：合格。	

9	GX-B1343/21-9-23042	2023. 9. 1	<ol style="list-style-type: none"> 1. 矿井总风量：8912.4m³/min； 2. 主通风机风量：9076.3m³/min； 3. 矿井有效风量：7247.0m³/min； 4. 矿井有效风量率：79.8%； 5. -155m水平风机4657.8m³/min，-305m水平风机4418.5m³/min； 6. 机站风压：-155m水平风机1030Pa，-305m水平风机1010Pa； 7. 矿井通风阻力：东风井通风系统1013.4Pa；西风井通风系统999.7Pa。 	
10	GX-B1347/21-9-23028	2023. 9. 1	<ol style="list-style-type: none"> 1. 风量（风速）合格率：100%，大于65%，合格； 2. 风质合格率：100%，大于90%，合格； 3. 作业环境空气质量合格率：100%，大于60%，合格； 4. 矿井有效风量率79.8%，大于60%，合格； 5. 风机全压效率为71.6%，大于70%，合格； 6. 风量供需比1.56，符合$1.32 \leq \beta \leq 1.67$要求，合格； 7. 综合指标91.1%，大于72%，合格。 	

11	GX-B1347/21-9-23035	2023年9月4日	<ol style="list-style-type: none">1. 风量（风速）合格率：100%，大于65%，合格；2. 风质合格率：100%，大于90%，合格；3. 作业环境空气质量合格率：100%，大于60%，合格；4. 矿井有效风量率69.8%，大于60%，合格；5. 风机全压效率为71.0%，大于70%，合格；6. 风量供需比1.63，符合$1.32 \leq \beta \leq 1.67$要求，合格；7. 综合指标89.0%，大于72%，合格。	
----	---------------------	-----------	--	---