

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|----|---------------------|-------------|---------|---|
| 61 | GX-B1310/21-4-24235 | 2025. 1. 20 | 符合标准要求。 |  A photograph showing a worker in a blue uniform and yellow hard hat standing on a blue metal structure, possibly a staircase or walkway, at an industrial site. A timestamp '2024.12.30' is visible in the bottom right corner. |
| 62 | GX-B1310/21-4-24236 | 2025. 1. 20 | 符合标准要求。 |  A photograph of a worker in a blue uniform and yellow hard hat working on a structure. The worker is wearing green gloves and is focused on a task. A timestamp '2024.12.30' is visible in the bottom right corner. |
| 63 | GX-B1310/21-4-24237 | 2025. 1. 20 | 符合标准要求。 |  A photograph showing a worker in a blue uniform and yellow hard hat standing on a blue metal structure with yellow railings. The worker is looking towards the camera. A timestamp '2024.12.30' is visible in the bottom right corner. |

| | | | | |
|----|---------------------|-------------|----------|--|
| 64 | GX-B1306/23-4-24011 | 2025. 1. 20 | 综合判定：合格。 |  |
| 65 | GX-B1304/21-4-24005 | 2025. 1. 22 | 综合判定：合格 |  |
| 66 | GX-B1301/23-4-25001 | 2025/1/20 | 综合判定：合格。 |  |

| | | | | |
|----|---------------------|-------------|----------------------|--|
| 67 | GX-B1301/23-4-25002 | 2025. 1. 20 | 综合判定：合格。 |  |
| 68 | GX-B1328/20-4-25003 | 2025. 1. 22 | 本次共检绝缘手套6只，6只所检项目合格。 |  |
| 69 | GX-B1328/20-4-25004 | 2025. 1. 22 | 本次共检绝缘鞋8只，8只所检项目合格。 |  |

| | | | | |
|----|---------------------|-------------|--------------------------|--|
| 70 | GX-B1328/20-4-25005 | 2025. 1. 22 | 本次共检绝缘杆2只，2只所检项目合格。 |  |
| 71 | GX-B1328/20-4-25006 | 2025. 1. 22 | 本次共检验电器3支，3支所检项目合格。 |  |
| 72 | GX-B1328/20-4-25007 | 2025. 1. 22 | 本次共检便携式短路接地线3套，3套所检项目合格。 |  |

| | | | | |
|----|---------------------|-------------|--------|--|
| 73 | GX-B1310/21-4-25002 | 2025. 1. 23 | 符合标准要求 |  2025 1 8 |
| 74 | GX-B1310/21-4-25003 | 2025. 1. 23 | 符合标准要求 |  2025 1 8 |
| 75 | GX-B1310/21-4-25009 | 2025. 1. 23 | 符合标准要求 |  2025 1 8 |

| | | | | |
|----|---------------------|-------------|--|--|
| 76 | GX-B1310/21-4-25010 | 2025. 1. 23 | 符合标准要求 |  |
| 77 | GX-B1598/24-4-25001 | 2025. 1. 23 | 实测钢丝绳有效截面积 损失百分比最大为 1.55%，小于5%为正常。 |  |
| 78 | GX-B1598/24-4-25002 | 2025. 1. 23 | 实测钢丝绳有效截面积 损失百分比最大为 1.80%，小于5%为正常。 |  |

| | | | | |
|----|---------------------|-------------|---|--|
| 79 | GX-B1598/24-4-25003 | 2025. 1. 23 | <p>实测钢丝绳有效截面积 损失百分比最大为 1.82%，小于5%为正常。</p> |  |
| 80 | GX-B1598/24-4-25004 | 2025. 1. 23 | <p>实测钢丝绳有效截面积 损失百分比最大为 0.79%，小于5%为正常。</p> |  |
| 81 | GX-B1598/24-4-25005 | 2025. 1. 23 | <p>实测钢丝绳有效截面积 损失百分比最大为 2.13%，小于5%为正常。</p> |  |

| | | | | |
|----|---------------------|-------------|---|---|
| 82 | GX-B1598/24-4-25006 | 2025. 1. 23 | <p>实测钢丝绳有效截面积 损失百分比最大为 1.52%，小于5%为正常。</p> |  <p>2025.1.16</p> |
| 83 | GX-B1598/24-4-25007 | 2025. 1. 23 | <p>实测钢丝绳有效截面积 损失百分比最大为 2.02%，小于5%为正常。</p> |  <p>2025.1.16</p> |
| 84 | GX-B1598/24-4-25008 | 2025. 1. 23 | <p>实测钢丝绳有效截面积 损失百分比最大为 2.32%，小于5%为正常。</p> |  <p>2025.1.16</p> |

| | | | | |
|----|---------------------|-------------|--|--|
| 85 | GX-B1598/24-4-25009 | 2025. 1. 23 | 实测钢丝绳有效截面积 损失百分比最大为 1.54%，小于5%为正常。 |  |
| 86 | GX-B1598/24-4-25010 | 2025. 1. 23 | 实测钢丝绳有效截面积 损失百分比最大为 0.73%，小于5%为正常。 |  |
| 87 | GX-B1598/24-4-25011 | 2025. 1. 23 | 实测钢丝绳有效截面积 损失百分比最大为 2.58%，小于5%为正常。 |  |

| | | | | |
|----|---------------------|-------------|--|---|
| 88 | GX-B1598/24-4-25012 | 2025. 1. 23 | 实测钢丝绳有效截面积 损失百分比最大为 2.39%，小于5%为正常。 |  |
| 89 | GX-B1302/23-4-25001 | 2025. 1. 24 | 综合判定：合格。 |  |