


序号	报告编号	发布日期	结论	影像资料
118	GX-B1382/21-4-23013	2023. 9. 27	所检项目合格。	
119	GX-B1321/20-4-23923	2023. 9. 27	所检项目合格。	
120	GX-B1309/21-4-23003	2023. 9. 27	所检项目合格。	

121	GX-B1309/21-4-23004	2023. 9. 27	所检项目合格。			
122	GX-B1500/21-4-23007	2023. 9. 27	综合判定：合格。 。			
123	GX-B1500/21-4-23008	2023. 9. 27	综合判定：合格。 。			

124	GX-B1500/21-4-23009	2023. 9. 27	综合判定：合格。 。		
125	GX-B1500/21-4-23010	2023. 9. 27	综合判定：合格。 。		
126	GX-B1500/21-4-23011	2023. 9. 27	综合判定：合格。 。		

127	GX-B1500/21-4-23012	2023. 9. 27	综合判定：合格。 。			
128	GX-B1500/21-4-23013	2023. 9. 27	综合判定：合格。 。			
129	GX-B1500/21-4-23014	2023. 9. 27	综合判定：合格。 。			

130	GX-B1500/21-4-23015	2023. 9. 27	综合判定：合格。 。	
131	GX-B1304/21-4-23006	2023. 9. 27	综合判定：合格。 。	
132	GX-B1303/21-4-23016	2023. 9. 27	综合判定：合格	


133	GX-B1309/21-4-23005	2023. 9. 28	所检项目合格	
134	GX-B1500/21-4-23016	2023. 9. 28	综合判定：合格	
135	GX-B1500/21-4-23017	2023. 9. 28	综合判定：合格	

136	GX-B1500/21-4-23018	2023. 9. 28	综合判定：合格	
137	GX-B1500/21-4-23019	2023. 9. 28	综合判定：合格	
138	GX-B1500/21-4-23020	2023. 9. 28	综合判定：合格	

139	GX-B1500/21-4-23021	2023. 9. 28	综合判定：合格	
140	GX-B1305/21-4-23005	2023. 9. 28	综合判定：合格	
141	GX-B1307/20-4-23023	2023. 9. 28	综合判定：合格。 。	

142	GX-B1307/20-4-23024	2023. 9. 28	综合判定：合格。 。	
143	GX-B1307/20-4-23025	2023. 9. 28	综合判定：合格。 。	
144	GX-B1307/20-4-23026	2023. 9. 28	综合判定：合格。 。	

145	GX-B1307/20-4-23027	2023. 9. 28	综合判定：合格。 。	
146	GX-B1328/20-4-23191	2023. 9. 28	本次共检绝缘手套24只，24只所检项目合格。	
147	GX-B1328/20-4-23192	2023. 9. 28	本次共检绝缘鞋24只，24只所检项目合格。	

148	GX-B1328/20-4-23193	2023. 9. 28	本次共检验电器 10支，10支所检 项目合格。		
149	GX-B1328/20-4-23194	2023. 9. 28	本次共检短路接 地线10套，10套 所检项目合格。		
150	GX-B1328/20-4-23195	2023. 9. 28	所检项目合格。		

151	GX-B1304/21-4-23007	2023. 9. 28	综合判定：合格	
152	GX-B1598/21-4-23025	2023. 9. 27	实测钢丝绳有效截面积损失百分比最大为1.10%，小于5%为正常。	
153	GX-B1598/21-4-23026	2023. 9. 27	实测钢丝绳有效截面积损失百分比最大为0.56%，小于5%为正常。	

154	GX-B1598/21-4-23027	2023. 9. 27	<p>实测钢丝绳有效截面积损失百分比最大为1.10%，小于5%为正常。</p>			
155	GX-B1598/21-4-23028	2023. 9. 27	<p>实测钢丝绳有效截面积损失百分比最大为1.94%，小于5%为正常。</p>			
156	GX-B1598/21-4-23029	2023. 9. 27	<p>实测钢丝绳有效截面积损失百分比最大为2.26%，小于5%为正常。</p>			

157	GX-B1598/21-4-23030	2023. 9. 27	实测钢丝绳有效截面积损失百分比最大为1.97%，小于5%为正常。	
158	GX-B1598/21-4-23031	2023. 9. 27	实测钢丝绳有效截面积损失百分比最大为0.08%，小于5%为正常。	
159	GX-B1598/21-4-23032	2023. 9. 27	实测钢丝绳有效截面积损失百分比最大为0.13%，小于5%为正常。	

160	GX-B1598/21-4-23033	2023. 9. 27	<p>实测钢丝绳有效截面积损失百分比最大为0.14%，小于5%为正常。</p>			
161	GX-B1598/21-4-23034	2023. 9. 27	<p>实测钢丝绳有效截面积损失百分比最大为0.80%，小于5%为正常。</p>			
162	GX-B1310/21-4-23149	2023. 9. 27	符合标准要求			

163	GX-B1310/21-4-23150	2023. 9. 27	符合标准要求	
164	GX-B1310/21-4-23151	2023. 9. 27	符合标准要求	
165	GX-B1598/21-4-23035	2023. 9. 28	<p>实测钢丝绳有效截面积损失百分比最大为0.61%，小于5%为正常。</p>	

166	GX-B1598/21-4-23036	2023. 9. 28	实测钢丝绳有效截面积损失百分比最大为2.82%，小于5%为正常。	
167	GX-B1307/20-4-23017	2023. 9. 28	综合判定：合格。	
168	GX-B1307/20-4-23018	2023. 9. 28	综合判定：合格。	

169	GX-B1307/20-4-23019	2023. 9. 28	综合判定：合格。 。		
170	GX-B1307/20-4-23020	2023. 9. 28	综合判定：合格。 。		
171	GX-B1310/21-4-23154	2023. 9. 28	符合标准要求		

172	GX-B1310/21-4-23152	2023. 9. 28	符合标准要求	
173	GX-B1310/21-4-23153	2023. 9. 28	符合标准要求	
174	GX-B1328/20-4-23189	2023. 9. 28	本次共检绝缘手套60只，60只所检项目合格。	

175	GX-B1328/20-4-23190	2023. 9. 28	本次共检绝缘鞋 60只，60只所检 项目合格。	
-----	---------------------	-------------	-------------------------------	---