




序号	报告编号	发布日期	结论	影像资料
37	GX-B1598/24-6-24141	2024/11/15	实测钢丝绳有效截面积损失百分比最大为2.88%，小于5%为正常。	
38	GX-B1598/24-6-24142	2024/11/15	实测钢丝绳有效截面积损失百分比最大为2.61%，小于5%为正常。	

39	GX-B1598/24-6-24143	2024/11/15	实测钢丝绳有效截面积损失百分比最大为2.97%，小于5%为正常。	
40	GX-B1598/24-6-24144	2024/11/15	实测钢丝绳有效截面积损失百分比最大为2.21%，小于5%为正常。	
41	GX-B1598/24-6-24145	2024/11/15	实测钢丝绳有效截面积损失百分比最大为2.16%，小于5%为正常。	

42	GX-B1598/24-6-24146	2024/11/15	实测钢丝绳有效截面积损失百分比最大为2.15%，小于5%为正常。	 2024 10 31
43	GX-B1598/24-6-24138	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为2.01%，小于5%为正常。	 2024 11 01
44	GX-B1598/24-6-24139	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为2.37%，小于5%为正常。	 2024 11 01

45	GX-B1598/24-6-24140	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为2.21%，小于5%为正常。	
46	GX-B1598/24-6-24147	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为1.85%，小于5%为正常。	
47	GX-B1598/24-6-24148	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为1.48%，小于5%为正常	

48	GX-B1598/24-6-24149	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为1.83%，小于5%为正常。	
49	GX-B1598/24-6-24150	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为1.37%，小于5%为正常。	
50	GX-B1598/24-6-24151	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为1.86%，小于5%为正常。	

51	GX-B1598/24-6-24152	2024. 11. 16	实测钢丝绳有效截面积损失百分比最大为1.75%，小于5%为正常。		
52	GX-B1428/21-6-24025	2024/11/20	无缺陷迹痕显示		
53	GX-B1428/21-6-24026	2024/11/20	无缺陷迹痕显示		

54	GX-B1428/21-6-24027	2024/11/20	无缺陷迹痕显示			
55	GX-B1428/21-6-24028	2024/11/20	无缺陷迹痕显示			
56	GX-B1428/21-6-24029	2024/11/20	无缺陷迹痕显示			

57	GX-B1428/21-6-24030	2024/11/20	无缺陷迹痕显示	
58	GX-B1428/21-6-24031	2024/11/20	无缺陷迹痕显示	
59	GX-B1428/21-6-24032	2024/11/20	无缺陷迹痕显示	