

序号	报告编号	发布日期	结论	影像资料
15	GX-B1303/21-6-24042	2025/1/8	综合判定合格	 <p>2024-12-25</p>
16	GX-B1303/21-6-24043	2025/1/8	综合判定合格	 <p>2024-12-25</p>

17	GX-B1328/20-6-25001	2025/1/9	本次共检验电器1支，1支所检项目合格。			
18	GX-B1328/20-6-25002	2025/1/9	本次共检验绝缘杆1组，1组所检项目合格。			
19	GX-B1328/20-6-25003	2025/1/9	本次共检验便携式接地和接地短路装置1组，1组所检项目合格。			

20	GX-B1310/21-6-24403	2025/1/8	符合标准要求		 <p>2024 12 26</p>
21	GX-B1310/21-6-24404	2025/1/8	符合标准要求		 <p>2024 12 26</p>
22	GX-B1427/21-6-24406	2025/1/8	符合标准要求		 <p>2024 12 26</p>

23	GX-B1598/24-6-24191	2025/1/10	实测钢丝绳有效截面积损失百分比最大为0.20%，小于5%为正常。	
24	GX-B1598/24-6-24192	2025/1/10	实测钢丝绳有效截面积损失百分比最大为0.19%，小于5%为正常。	
25	GX-B1598/24-6-24193	2025/1/10	实测钢丝绳有效截面积损失百分比最大为3.74%，小于5%为正常。	

26	GX-B1598/24-6-24194	2025/1/10	实测钢丝绳有效截面积损失百分比最大为3.96%，小于5%为正常。	
27	GX-B1598/24-6-24195	2025/1/10	实测钢丝绳有效截面积损失百分比最大为3.45%，小于5%为正常。	
28	GX-B1598/24-6-24196	2025/1/10	实测钢丝绳有效截面积损失百分比最大为3.23%，小于5%为正常。	

29	GX-B1598/24-6-24197	2025/1/10	<p>实测钢丝绳有效截面积损失百分比最大为3.81%，小于5%为正常。</p>	
30	GX-B1598/24-6-24198	2025/1/10	<p>实测钢丝绳有效截面积损失百分比最大为3.63%，小于5%为正常。</p>	
31	GX-B1328/20-6-25004	2025/1/10	<p>本次共检绝缘手套4只，4只绝缘手套所检项目合格。</p>	

32	GX-B1328/20-6-25005	2025/1/10	<p>本次共检全橡胶绝缘胶靴4只，4只全橡胶绝缘胶靴所检项目合格。</p> <p>。</p>			
33	GX-B1328/20-6-25006	2025/1/10	<p>所检项目合格。</p>			
34	GX-B1328/20-6-25007	2025/1/10	<p>本次共检验绝缘杆2组，2组绝缘杆所检项目合格。</p> <p>。</p>			

35	GX-B1324/21-6-25001	2025/1/16	所检项目合格	 <p>2025-01-03</p>
36	GX-B1310/21-6-24414	2025/1/16	所检项目合格	 <p>2024-12-17</p>
37	GX-B1328/20-6-24142	2025/1/14	所检项目合格	 <p>2024-12-30</p>