

序号	报告编号	发布日期	结论	影像资料
30	GX-B1534/20-6-23022	2023/12/8	所检项目合格	 <p>2023 11 22</p>
31	GX-B1534/20-6-23023	2023/12/8	所检项目合格	 <p>2023 11 22</p>

32	GX-B1534/20-6-23024	2023/12/8	所检项目合格	 <p>2023 11 22</p>
33	GX-B1534/20-6-23025	2023/12/8	所检项目合格	 <p>2023 11 22</p>
34	GX-B1534/20-6-23026	2023/12/8	所检项目合格	 <p>2023 11 22</p>

35	GX-B1534/20-6-23027	2023/12/8	所检项目合格	
36	GX-B1598/21-6-23081	2023/12/8	实测钢丝绳有效截面积损失百分比最大为1.21%，小于5%为正常。	
37	GX-B1598/21-6-23082	2023/12/8	实测钢丝绳有效截面积损失百分比最大为1.25%，小于5%为正常。	

38	GX-B1598/21-6-23083	2023/12/8	实测钢丝绳有效截面积损失百分比最大为1.28%，小于5%为正常。	 <p>2023 11 24</p>
39	GX-B1598/21-6-23084	2023/12/8	实测钢丝绳有效截面积损失百分比最大为1.26%，小于5%为正常。	 <p>2023 11 24</p>
40	GX-B1598/21-6-23085	2023/12/8	实测钢丝绳有效截面积损失百分比最大为2.10%，小于5%为正常。	 <p>2023 11 24</p>

41	GX-B1598/21-6-23086	2023/12/8	实测钢丝绳有效截面积损失百分比最大为1.89%，小于5%为正常。	
42	GX-B1495/20-6-231375	2023/12/7	所检项目合格	
43	GX-B1328/20-6-23161	2023/12/8	本次共检绝缘手套4只，4只绝缘手套所检项目合格。	

44	GX-B1328/20-6-23162	2023/12/8	本次共检全橡胶绝缘靴4只，4只全橡胶绝缘靴所检项目合格。	 <p>2023 12 04</p>
45	GX-B1520/20-6-23121	综合判定合格	2023/12/13	 <p>2023 12 07</p>
46	GX-B1309/21-6-23035	所检项目合格	2023/12/13	 <p>2023 12 11</p>